

PORC+ DRILL BIT TIPS FOR DRILLING PORCELAIN TILE

For best results, follow these directions:



- Tile should be on a level surface
- Operate drill motor between 400 - 600 RPMs – higher speeds will damage bit, reducing the number of holes the bit can effectively drill
- First, drill a small hole with a 5/32" PORC+ bit and then use a larger bit depending on hole required (3/16", 1/4", 5/16", 3/8", or 1/2")
- Use some pressure during drilling; however, too much pressure can make the bit move and cause the hole not to be centered as marked and could also cause the tile to break
- To extend the life of the bit, let it cool down for several minutes between each hole

Follow all safety requirements and use proper safety protection when using ARTU products.



If you have any questions and/or need additional information, contact Customer Service at (800) 367-2788 or sales@artu.com